



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 28, 2013

Reviewed: PBS

Mine Name: Lisbon Valley Copper	Permit Number: E/037/0183 & M/037/0088
Operator Name: Lisbon Valley Mining Company LLC	Inspection Date: 6/12/2013
Inspector(s): Mike Bradley/Wayne Western	Time: 10:00a
Other Participants: Lantz Indergard, Rebecca Doolittle	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Reclamation of exploration sites; introduction to LVMC staff, Becky Doolittle, and site familiarization

Inspection Summary:

Bond escalation in progress, pending reorganized mine plan to be submitted. Reclaimed exploration areas have been graded, but vegetation is just starting, currently dominated by Russian thistle.

Photos were taken to document site conditions

Conclusions and Recommendations:

Grading of exploration areas looked good, but will likely need another growing season for vegetation.

Inspector's Signature

Mike Bradley

CC: PBB;mpb;eb

Lantz Indergard, LVMC

Rebecca Doolittle, BLM

O:\M037-SanJuan\E0370183-LisbonValley-Summo\Draft\Insp-06282013.doc



Photo 1: Exploration site, Russian thistle emerging



Photo 2: Exploration site



Photo 3: Centennial Pit-north



Photo 4: Centennial Pit-south